

Pro	Project Title:						All Hadden Main Contract Projects							
Tas	Task:						Generic COVID-19 F	Risk A	Assessme	nt - Site				
		obability Severity						The following guidelines should be applied to risk factors after control measures have been applied: Risk Factors After Control Measures						
	Probability				Severity			1-5 0	к то) P	ROCEED			
								х			6 – 10 FURTHE	R CO	N	TROL MEASURES
							Severity		SHOULD BE APPLIED. SEEK FURTHER					
									GUI		GUIDA	ANCE IF UNSURE		
5	Very Likely	5	Fatality		Major Env. Ir	ıcide	nt	Low Risk = 1 to 5						
4	Likely	4	Major Injury		Severe Dama	ge			= 6 to 10 12+ UNACCEPTABLE – DO NO					
3	Probable	3	Medical Inju	ry	Damage			Medium Risk :			DO NOT PROCEED			
2	Possible	2	Minor Injury		Small Impact									
1	Very Unlikely	1	No Injury		No Env. Impa	ıct		High Risk =	: 12-	+				
Pei	sons at Risk													
E	Employees	С	Contractors	A Age		Ager	ncy	S Self Employed		Р	F	Public		
Rel	Relevant Legislation:			Health and Safety at Work Act. 1974			Management of Health & Safety at Work Regulations. 1999							
PPI	PPE at Work Regulations. 1992			The Work at Height Regulations. 2005 Manual Handling Operation Regulati			lation	ns.	1992					
Pro	vision & Use of Work Equipment	Regu	lations. 1998				ulations. 2007							

Prepared By:	Andy Robertson	Position:	Health & Safety Manager	Date:	02/11/2020
Approved By:	Paul Shankland	Position:	Construction Director	Date:	02/11/2020

HCL IMS Ref: HS77 Issue: 2 Page 1 of 13



Project Title:		All Hadden Main Contract Projects	
Task:		Generic COVID-19 Risk Assessment - Site	
1. Worker failing to declare own symptoms or contact with possible/known carrier.	Exposing other workers to the virus. Persons at Risk: E-C-A-S-P	Risk Factor Before control: Solution So	 Control Measure: All workers must only arrive at work if you are well and have no COVID-19 symptoms. All workers will be required to answer daily, prescreening questions prior to attending/accessing site. Covid-19 signage will be displayed at Site Entrance and throughout site acting as a reminder to workers. All workers will be informed again of this duty on completion of the Covid-19 Standard Operating Procedures and Site Rules. All workers will be required to undertake a full Site Induction prior to being able to start work, covering Covid-19 requirements and control measures. This Risk Assessment must be briefed to all workers
Hazard:	Risk:	Risk Factor Before control:	and visitors to site. Control Measure: Risk Factor After Control:
2. Worker transport/ travelling to and from their place of work.	Risk of contamination from touching un sanitised surfaces. Risk of coming into contact with a carrier of the virus. Persons at Risk: E-C-A-S-P	5	 Workers should travel to and from site alone using their own transport, where possible. Where Public Transport must be used, the current guidance relating to face covering mut be adhered to. Other means of transport should be considered, where possible, such as using a bicycle or walking. General site-specific parking arrangements will be communicated at site, where available. Additional care and attention to maintain current physical distancing guidelines must be taken when entering/exiting your vehicle. Workers are responsible for sanitising their own vehicles. Workers are to ensure that they sanitise/wash their hands, immediately on arrival at home.

HCL IMS Ref: HS77 Issue: 2 Page 2 of 13





Hazard:	Risk: Risk Factor Before control: Co		Control Measure:	Risk Factor After Control:
3. Arrival at Site including Access/Egress	Risk of transmitting the Coronavirus to personnel within the site. Persons at Risk: E-C-A-S-P	5 4 20 3 2 2 1 1 2 3 4 5 Severity	 Workers who are unwell with symptoms of Coronavirus (Covid-19) should not travel to or attend the workplace and should follow the Governments guidelines on self-isolation and test and protect. Entry to site will be restricted to site workers and essential personnel only with all non-essential visitors being refused entry. Workers must TEXT/PHONE Site Manager on every entry/exit to site to allow the site register to be completed on their behalf. Workers must sanitise their hands at every entry/exit to site with the sanitiser provided. A strict 2m physical distance must be maintained by all in the event of queueing on site. Markings and signage will be displayed for guidance. Site Personnel must not enter the Site Office without prior TEXT/TELEPHONE to the Site Manager - contact number will be displayed. Staggered start/stop times have been introduced for internal/external trades. Where a site induction is required, TEXT/CALL Site Manager, DO NOT enter Site Office until advised it is safe to do so. The wearing of face coverings, on all Hadden construction sites is a mandatory requirement any face coverings must be donned prior to entering. Genuine reasons for not complying with the mandatory wearing of face coverings is to be immediately brought to the attention of the Site Manager. 	5 4 3 2 2 2 1 5 5 0 1 2 3 4 5 Severity

HCL IMS Ref: HS77 Issue: 2 Page **3** of **13**



Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:
4. General Workplace Planning activities, traversing throughout the site, working from scaffolding etc.	Risk of transmitting the Virus to personnel within the site. Persons at Risk: E-C-A-S-P	5	 All work tasks must be properly planned to follow the Hierarchy of Risk Controls. Eliminate-Reduce-Isolate-Control-PPE-Discipline. Workers must adhere to Hadden Site Operating Procedures regarding Physical Distancing, Hand Hygiene and Face Coverings. Site Management are to be considered COVID-19 Compliance Officers and will immediately remove any non-compliant personnel from site. Site Management will continuously reiterate the Site Social Distancing, Hand Hygiene, Face Coverings, and PPE requirements. Site mandatory signage must be adhered to at all times Any one-way systems/passing points must be followed. 	5 4 3 2 2 2 1 5 5 0 1 2 3 4 5 Severity
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:
5. Hand Hygiene. Washing or Sanitising.	Risk of infection due to contaminated hands. Risk of infection through hand to mouth contact or by touching your face or eyes. Persons at Risk: E-C-A-S	5 4 20 3 20 3 2 1 0 1 2 3 4 5 Severity	 All workers must maintain good personal hygiene. Handwashing/sanitising signage will be displayed at welfare facilities/canteens and throughout the site. Additional time will be permitted for workers to sanitise their hands correctly, where required. Hands should be washed more often with soap and water for at least 20 seconds or use hand sanitiser if soap and water are not available. Wash your hands immediately on arrival to site, prior to leaving site and as soon as you get home. Wash your hands after you blow your nose, sneeze, or cough, prior to eating or handling food, and prior to operating tools or equipment. Avoid touching your eyes, nose, and mouth with unwashed hands. Report any known signs of Covid-19 immediately to the Site Manager. Cover any coughs or sneezes with a sleeve or tissue, then throw the tissue directly into a waste bin and then wash your hands. 	5 4 3 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9

HCL IMS Ref: HS77 Issue: 2 Page 4 of 13



Hazard: Risk: Ris		Risk Factor Before control:	Control Measure:	Risk Factor After Control:
6. Failure to maintain a 2m physical distance from others.	Risk of infection from contaminated droplets. Persons at Risk: E-C-A-S-P	5 4 20 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	 One Trade One Area has been introduced to reduce the likelihood for crowding within the same area. Signage, Site Rules, Standard Operating Procedures, and this Risk Assessment all provide guidance. Workers are encouraged to enforce this guidance. Physical Distancing signage is displayed throughout site Any work requiring individuals to work closer than 2.0m must be Risk Assessed prior to the work starting and include suitable and sufficient control measures to mitigate the risk of infection to the work party. The Risk Assessment will be retained by the Site Team and used for contact tracing purposes, where required. 	5 4 3 2 2 2 1 5 5 0 1 2 3 4 5 Severity
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:
7. Communal Areas and Welfare Facilities	Risk of infection, cross contamination due to being unable to maintain social distancing and overcrowding within areas such as canteens, toilets, and drying room facilities. Persons at Risk: E-C-A-S-P	5 4 20 3 20 3 2 1 1 0 1 2 3 4 5 Severity	 The default position on site is to maintain a Physical Distance of 2.0m from others where possible and, that any work required to be carried out within 2.0m of others must only start, after a specific Risk Assessment has been completed, Site Managers will split/stagger meal/break times where required and workers are encouraged to stay on site once entered, to take any breaks alone and to bring their own food. Alternative locations for taking breaks are permitted and attending local shops should be discouraged. Tables/chairs have been positioned to ensure that Physical Distancing can be maintained, and the use of the fridge is not permitted at this time. Tables, kettles, microwaves, and communal surfaces must be sanitised after use. Toilet are one in one out at this time and the female toilet will be available for use by all. Workers are responsible for sanitising the facilities after use such as door handles, locks, and toilet flush. Face Coverings must be worn within any communal areas and welfare facilities and can be removed once seated in preparation to eat/drink. 	5 4 3 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9

HCL IMS Ref: HS77 Issue: 2 Page **5** of **13**



Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:		
8. Exposure from contact with contaminated surface	Risk of infection, cross contamination Persons at Risk: E-C-A-S-P	5	 Workers must follow strict personal hygiene standards. Do not shake hands. Do not share items such as pens, phones, hand tools. ONE TRADE ONE AREA. Increased, enhanced cleaning measures have been implemented across all Hadden sites. Workers are advised to self-sanitise prior to and after using communal areas/items. Hand to mouth contact is to be avoided. Avoid touching eyes, nose, mouth with unwashed hands. 	5 4 3 2 2 2 1 5 5 0 1 2 3 4 5 Severity		
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:		
9. Person requiring First Aid whilst at work.	Risk of increased injury to injured party. Risk of cross contamination to first aider. Persons at Risk: E-C-A-S-P	5	 For minor injuries, First Aiders should advise the Injured Party on how to self-help, e.g. applying a plaster on their own. First Aider and Injured Party are to maintain a 2.0m distance and face side on where possible. Enhanced PPE must be used at this time whilst performing First Aid duties such as: Face Visor, Disposable Apron, Disposable Gloves, and Face Mask. Face Shield is to be used in all CPR attempts. 	5 4 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:		
10. Plant Operators.	Risk of infection due to un-sanitised surfaces. Persons at Risk: E-C-A	5	 Plant operators must sanitise all frequently touched areas prior to the changing of operators and at the end of each shift. An example of surfaces to be wiped down include, handbrakes, keys & fobs, door handles, steering wheel, gear shift, operating levers, radio, GPS & other buttons & dials, seat/seat belts. Operators should keep the windows of enclosed machinery open for ventilation and avoid touching their face at all times. Face Coverings must be worn, immediately on exiting the cab, no matter for how short a duration. 	5 4 3 4 3 2 2 2 1 5 5 0 1 2 3 4 5 Severity		

HCL IMS Ref: HS77 Issue: 2 Page 6 of 13



Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:	
11. Machinery, Equipment and Tooling.	Cross contamination from one individual/surface to another. Persons at Risk: E-C-A-S-P	5 4 20 3 2 2 2 1 0 1 2 3 4 5 Severity	 Operators must ensure that any tools and equipment used are properly sanitised prior to use. An attempt should be made to keep the same operator using the same item as much as possible. The sharing of individual tools should be avoided where possible. 	5 4 3 4 5 Severity	
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:	
12. Deliveries to site.	Risk of cross contamination to personnel not maintaining a 2m social distance. Persons at Risk: E-C-A-S-P	5 4 12 12 12 12 13 14 5 Severity	 All delivery drivers must call Site Manager on arrival – contact details available at the front gate. Delivery driver must fully unload and maintain 2.0m Physical Distance from site workers. If assistance is required, the driver must prepare his load, then return to his cab. On completion, hands must be washed/sanitised. No delivery notes are to be signed at this point. Delivery drivers are also required to wear face coverings whilst on site, where possible. 	5 4 3 4 3 2 1 4 0 1 2 3 4 5 Severity	
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:	
13. Underlying health conditions.	Risk of infection to vulnerable, shielding persons. Risk to "at risk groups" Persons at Risk: E-C-A-S-P	5	 Anyone who is at an increased risk of severe illness from COVID-19 is strongly advised to work at home and be particularly stringent in regard to social distancing. Anyone identified as extremely vulnerable will be advised by their health authority and must follow the governments advice. Persons living with or caring for anyone that is in the HSE's "at risk" category must consider if there is a heightened risk from attending work. Anyone living with a person who is at increased risk of severe illness, or an extremely vulnerable person, should stringently follow the current guidance on Physical Distancing and minimise contact outside the home. 	5 4 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	

HCL IMS Ref: HS77 Issue: 2 Page **7** of **13**



Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:		
14. Cleaning	Risk of infection or cross contamination due to poor or reduced site 5 4 20 3		 An increased professional cleaning regime has been introduced at each site and is specific to that site in relation to size and personnel. A daily site cleaning register will be maintained evidencing the frequency of the cleaning and by whom. Examples of frequently touched surfaces/objects to be wiped down include, taps, sinks, toilet flush/seats, door handles, handrails on stairways /scaffolding, lift/hoist controls, machinery/equipment controls, food preparation/eating surfaces. Rubbish bags must be collected and disposed of daily. It is the responsibility of the worker to ensure their work area is clean and any housekeeping and site standards are maintained. 	5 4 3 2 2 1 5 5 0 1 2 3 4 5 Severity		
Hazard:	Risk:	Risk Factor Before control:	Control Measure:	Risk Factor After Control:		
15. Positive Covid- 19 case identified on- site.	Risk of contamination throughout the site. Persons at Risk: E-C-A-S-P	5	 If a worker shows symptom of COVID-19 whilst at work, they should: Ensure their manager or supervisor is informed, return home immediately, avoid touching anything, cough or sneeze into a tissue and put it in a bin, or if they do not have tissues, cough and sneeze into the crook of their elbow. Once declared, HR/H&S departments must be notified. Skin to skin and face to face contact must be avoided. Individuals must follow the current Government guidance on self-isolation: https://www.gov.uk/government/publications/covid-19-stay-at-home-guidance/stay-at-home-guidance-for-households-with-possible-coronavirus-covid-19-infection The workplace will be decontaminated following Governmental guidance: https://www.gov.uk/government/publications/covid-19-decontamination-in-non-healthcare-settings/covid-19-decontamination-in-non-healthcare-settings 	5 4 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		

HCL IMS Ref: HS77 Issue: 2 Page 8 of 13



 Project Title:
 All Hadden Main Contract Projects

 Task:
 Generic COVID-19 Risk Assessment - Site

Personal Protective Equipment (PPE)

The following PPE shall, as a minimum, be used by the personnel undertaking tasks detailed within this Risk Assessment.





















неаа	
BS EN	
397:2012	





 Vis
 Hand

 ISO
 BS EN ISO

 171
 21420:2019

Eye

BS EN ISO

4007:2012

Face

SO BS EN

12 166:2002

Ears BS EN 458:2016

Dust EN 149: 2001 FFP3

Respiratory BS EN 136:1998

BS EN 361:2002

MANDATORY

TASK SPECIFIC

PPE Inspection/Maintenance Arrangements:

Issued users to check PPE before each use. PPE shall not be re-issued to another operative once used. Operatives shall ensure that damaged PPE is returned to their supervisor for replacement. The use and condition of PPE shall be checked during regular Safety Audits and Inspections.

Personnel to sign to confirm that they have read and fully understand this Risk Assessment and the control measures within.

PRINT NAME	SIGN NAME	DATE	PRINT NAME	SIGN NAME	DATE
1.			8.		
2.			9.		
3.			10.		
4.			11.		
5.			12.		
6.			13		
7.			14		
SITE MANAGER PRINT		SITE MANAGER SIGN		DATE	

HCL IMS Ref: HS77 Issue: 2 Page **9** of **13**



Coronavirus COVID-19 Help prevent infection. Physical Distancing Coronavirus Covid-19 Hand Hygiene Hand Hygiene ONE TRADE ONE Have you **PHYSICAL AREA** Sanitised **DISTANCING** your Hands? **Know the Signs**

HCL IMS Ref: HS77 Issue: 2

Coronavirus COVID-19 Help prevent infection.



HCL IMS Ref: HS77 Issue: 2



HCL IMS Ref: HS77 Issue: 2



Please wear a face covering

HCL IMS Ref: HS77 Issue: 2